

## ILLINOIS DEPARTMENT OF NATURAL RESOURCES

Office of Oil and Gas Resource Management One Natural Resources Way Springfield, Illinois 62702-1271



## HIGH VOLUME HORIZONTAL HYDRAULIC FRACTURING PERMIT APPLICATION HVHHF-10

References to "1-xx" or "§1-xx" are to the Hydraulic Fracturing Regulatory Act., 225 ILCS 732/1-1 et seq. References to "240.xxx" and "245.xxx" are to 62 Ill. Admin. Code 240 and 245, respectively.

## Attachment: TopsoilPreservationPlan

Please save attachment and use the file name above.

Topsoil Preservation Plan §1-35(b)(20); 245.210(b)(2), 245.410(d).

Please detail the plan to stockpile, stabilize, store, and segregate any topsoil and subsoil stripped from the site, as well as the proposed timeframe during which the site will be disturbed.



Woolsey Operating Company, LLC Woodrow #1H-310408-193 White County, Illinois High Volume Horizontal Hydraulic Fracturing Permit Application HVHHF-10: Topsoil Preservation Plan

## ATTACHMENT: Topsoil Preservation Plan

At the time of construction, topsoil will be stripped following vegetation removal, be stored separately from subsoil or other excavated material to avoid mixing during construction, storage and restoration. Topsoil will include all suitable growth medium present at site, as indicated by color or texture or supporting any sprigs of vegetation.

Topsoil will be wind-rowed to shallowest practical depth around the entire perimeter of well pad to create a berm that infiltrates/redirects/manages storm water while extending the viability of the topsoil.

Erosion control will be installed if necessary to ensure soil stays within the stockpile footprint. Stockpiles will be stabilized to avoid erosional losses using re-established native grasses and/or erosion mats. If topsoil stockpiles will remain longer than a growing season, the pile will be seeded with a cover crop.

Topsoil, subsoil, and underlying materials will be stored in separate piles.

The site will be disturbed from between 6 months and one year.

On April 22, 2016, 62 III. Adm. Code 240.1181 was repealed and the requirements found in that Section were incorporated into 62 III. Adm. Code 240.1180. As it is now impossible to comply with 62 III. Adm. Code 240.1181, the well site will be restored with the restoration requirements found in 62 III. Adm. Code 240.1180 and Section 1-95 of the Hydraulic Fracturing Regulatory Act, 225 ILCS 732/1-95.